MIG WIRE FEEDER MOTOR & FEEDER PARTS

WFMK-74-1

DESCRIPTION

Wire Feeder With Motor -5A/24V, 2 Pulleys

Also Available

5A/110V

-5A/42V, 10A/42V,

Standard V Roller Groove

TYPE

WFMK-74-2

DESCRIPTION

Wire Feeder With Motor -5A/24V, 2 Pulleys Standard V Roller Groove

TYP<u>E</u>

Also Available -5A/42V.

WFMK-76-1



DESCRIPTION

Wire Feeder With Motor -5A/24V, 2 Pulleys

Also Available -5A/42V,

TYPE

Standard V Roller Groove

WFMK-711



DESCRIPTION

Wire Feeder

Also Available -5A/42V, 15A/42V, 5A/110V

WFMK-710



DESCRIPTION

Wire Feeder With Motor (Wire Feeding Speed 18m/min) -24V, 4 Pulleys

TYPE

OTC® Adapter V Roller Groove

WFMK-79



DESCRIPTION

Panasonic® Adapter -18.3V, 2 Pulleys V Roller Groove

WFMK-712



DESCRIPTION

Wire Feeder With Motor (Wire Feeding Speed 18m/min) -18.3V, 2 Pulleys

TYPE

Panasonic® Adapter V Roller Groove

CWF-7401-25



CWF-7401-25



DESCRIPTION

Complete Wire Feeder Motor Assembly with Motor

ACCESSORIES



1

3

4 UAA-9-12

5 UAA-6

6 **UAA-4-11**

WG-WF-1

8 PA-79

9

10 FR-RG-1

11 FR-RGB-F 12 FR-RGB-H

13 WG-MLWF-1

14 WG-MLWF-2 15 WG-CNWF-1

CWG-710 Centre Wire Guide for WFMK-710

Roller guide with bush, High (Thickness of Bush = 16 mm) Wire Guide for Miller (58 x 10)

With Motor -5A/24V, 4 Pulleys Standard V Roller Groove

TYPE

TYPE

Wire Feeder With Motor



TYPE

Panasonic® Adapter V Roller Groove

DESCRIPTION **PART NO**

Upper Arm Assembly & Tightening Screw for WFMK-76-1 Upper Arm Assembly & Tightening Screw for WFMK-74-1, 74-2, 711 Wire Guide for Wire Feeders Pressure Arm with Roller & 2 Screws for WFMK-79

Upper Arm Assembly & Tightening Screw for WFMK-79, 712

Roller guide for PA-79 (Without Bush) Roller guide with bush, Flat (Thickness of Bush =12.35 mm)

Wire Guide for Miller (58 x 16) Wire Guide China Feeder (52 x 15)